Fire Management Statement



WALLACE BUSHLAND RESERVE, FRANKSTON

opportunity » growth » lifestyle

Approvals

FMS compilation	Michael Hansby, Analyst - Terramatrix
Approved by	Jarred Stevens & Alan Wallis, Frankston City Council
Approval date	23/04/2015

Version control

Date	Comments	Distribution
04/02/2015	Draft FMS	FCC
23/04/2015	Revised FMS incorporating FCC feedback	FCC

Description

Reserve name	Wallace Bushland Reserve
Suburb	Frankston
Perimeter roads	Wallace Avenue, Barwon Avenue
Other road access	Kiandra Court, Meribah Court, Wandella Road
Melway map ref	102 J6
Reserve size	3.7 ha
Reserve use	Recreation, conservation
BMO	No
BPA	Yes (full coverage)
Description	The Wallace Bushland Reserve is a small reserve with a mixture of remnant, revegetated and exotic canopy species. The native vegetation is confined to the north and the exotic vegetation (<i>Pinus pinaster</i>) is in the south. There is an area that is fenced on the south-western boundary that has been extensively re-vegetated by the 'Friends of Wallace Reserve' community group. There is a grassed, recreational area on the northern boundary. The predominant land use surrounding the reserve is residential.
Documents - generic	 Terramatrix (2013), Frankston City Council Natural Reserves Bushfire Management Strategy, Frankston City Council, Frankston. Nolan, R. and Cairns, M. (2008) <i>Fire Ecology Assessment for the City of Frankston's Natural Reserves</i>. SMEC Australia Pty. Ltd., Melbourne. Frankston City Council, (2013). <i>Natural Reserves Maintenance Manual</i>. Frankston City Council, Frankston.
Documents (reserve specific)	Terramatrix (2012). <i>Wallace Bushland Reserve; Natural Reserves Fire Management Zones</i> . Frankston City Council, Frankston.
Ecological Vegetation Classes	Damp Sands, Herb-rich Woodland (EVC 3).

Topography	The Wallace Bushland Reserve contains topography of moderate complexity. There is a moderate rise in slope from the north-west to the south-east, with a knoll being the high point on the south-east boundary (75m asl). Most of the reserve is of northerly/north-easterly aspect and of moderate slope (generally less than 10°), with one small area of out-cropping sandstone with slope of 12°.
Fire history (suspicious)	None
(Based on available	
information).	
Planned burn history	Western boundary, 2007.
Assets within	Fencing, signage.
Assets adjacent	Houses.
Asset exposure	Hazard to N, S, E, and W of assets.
Credible fire scenario	A local ignition on the north-western edge of the reserve, moving in a south-
	easterly direction for approximately 340m.

Current conditions and assessment

Community engagement

Document name	Published
Articles in local paper regarding fire safety (CFA, FCC)	As required
Social media posts regarding fire safety (CFA, FCC)	As required
FCC website	As required

Event name	Comments
CFA Fire Ready Meetings	As required
Meetings with Friends Groups	As required

Fuel management

APZ perimeter coverage	Western perimeter
APZ width	All greater than or equal to 6 m wide
Planned burns scheduled	No set date. Burn within tolerable fire interval
Other fuel management work	Refer to FCC Maintenance Manual for reserve specific
	actions

The formal APZ on the western boundary and the area of 'mown open-space' on the south-eastern boundary offer at least a 6m low fuel area adjacent to all private property. Further separation from the reserve vegetation is provided on the private property, as the houses are set back from the boundaries. Terramatirx considers the Fuel management arrangements in place at the Wallace Bushland Reserve to be of adequate width and condition.

	Assessment of current fuel management	Adequate	
e	Assessment of current fuer management	Adequate	

Access

Access at Wallace Bushland Reserve is shown on Map 1.

There are four formal access points (two tanker and two light 4x4 vehicle) on the perimeter of the Wallace Bushland Reserve. Tanker access into the reserve is confined to the western APZ area. Assuming fire services are able to open all vehicle gates and tracks, and areas designated as providing access are maintained, the level of access is deemed adequate.

Assessment of current access	Adequate
Recommendations	Maintain to ensure access during fire danger period
Meeting with CFA	As required
CFA personnel	(insert name)

Water supply

Water hydrants	The streets surrounding Wallace Bushland Reserve contain numerous hydrants. There are none within the reserve. (Refer Map 1)	
Static supply	There are no static water points in the reserve.	

Signage

Adequate fire safety information signage exists at the four major entrance points into the reserve. These signs contain information regarding no smoking and the prohibition of lighting fires within the reserve.

Recommendations

Туре	Action
Vegetation management	Maintain existing APZs and low fuel areas
Access	Maintain existing entrances and tracks to ensure both light 4x4 vehicle
ALLESS	and tanker access
Signage	None



Map 1 - Wallace Reserve, current conditions and fire history